

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB Basra	CERTIFICATION NO:	QC-SLB-25190-12A
Location:	WIRE LINE WORKSHOP	Job Order No:	QC-SLB-25190
Date of Examination:	21/July/2025	Next Inspection Date:	22/Jan/2026
Last Inspection		Last Proof Load Test Date	
02/Jan/2025		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION						QTY	SWL				
064m	LIFTING CLAMP Manufacture: NOV Lifting clamp assembly (lower clamp) Into two halves bolted together complete Of two lifting points one on each side. Constructed of welded steel plates 						01	3 TON				
Applicable Reference Standard:		BS EN 13155:2003 +A2:2009						SKID # 030				
* Is this the first examination after installation or assembly at a new site or location?						Was the examination carried out?						
		YES		NO	√	* Within an interval of 6 months?		YES	√	NO		
* If the answer to the above question is YES has the equipment been installed correctly?						* Within an interval of 12 months?		YES		NO	√	
		YES	√	NO		* By an examination scheme?		YES	√	NO		
						* After the occurrence of exceptional circumstances?		YES		NO	√	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None												
Is The Above A Defect Which Is Of Immediate Danger To Persons								YES			NO	√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)						NO		√	YES		By:	
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None												
** Visual And Dimension Check was Carried Out.												
Is This Equipment Safe To Operate?						Yes Accept		√	NO Reject			

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Abdullah		Ashraf Alsaad	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.