



Al Takamul Company for Engineering Services
Quality Control – Iraq

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25172-14
Location:	WIRE LINE WORKSHOP	Job Order No:	QC-SLB-25172
Date of Examination:	28/Jun/2025	Next Inspection Due:	27/Dec/2025
Last Inspection		Last Proof Load Test Date	
JULY-2024		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION										QTY	SWL
295727-6	ROUND WEBBING SLING FOR LOGIN UNIT RIG UP Material: NYLON Length: 16 ft Manufacturer: FARGAMEL Safety Factor: 7:1 										01	VERTICAL: 50,000 LBS CHOKER: 40,000 LBS BASKET: 10,000 LBS
Applicable Reference Standard:		BS EN 1492-1:2000+A1:2008										
* Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?							
	YES		NO	✓	* Within an interval of 6 months?		YES	✓	NO			
					* Within an interval of 12 months?		YES		NO	✓		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO		* By an examination scheme?		YES	✓	NO			
					* After the occurrence of exceptional circumstances?		YES		NO	✓		
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None												
Is The Above A Defect Which Is Of Immediate Danger To Persons							YES		NO	✓		
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)					NO	✓	YES		By:			
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None												
** Visual And Dimension Check was Carried Out.												
Is This Equipment Safe To Operate?					Yes Accept		✓	NO Reject				

LEE & ASNT Level II Inspector Name:	SIGNATURE: 	Authenticating This Report:	SIGNATURE:
Mohammed Abdullah		Ashraf Alsaad	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

