



Al Takamul Company for Engineering Services
Quality Control – Iraq

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25180-15
Location:	WIRE LINE WORKSHOP	Job Order No:	QC-SLB-25180
Date of Examination:	10/Jul/2025	Next Inspection Due:	09/Jan/2026
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION										QTY	SWL				
284740-29	ROUND WEBBING SLING FOR LOGIN UNIT RIG UP Material: Nylon Length: 4 ft Model: RCHPE40 Colour: Orange Safety Factor: 7:1 										01	VERTICAL: 40000 LBS CHOKER: 32000 LBS BASKET: 80000 LBS				
Applicable Reference Standard:		BS EN 1492-1:2000+A1:2008														
* Is this the first examination after installation or assembly at a new site or location?						Was the examination carried out?										
		YES		NO	√	* Within an interval of 6 months?				YES	√	NO				
						* Within an interval of 12 months?				YES		NO	√			
* If the answer to the above question is YES has the equipment been installed correctly?		YES	√	NO		* By an examination scheme?				YES	√	NO				
						* After the occurrence of exceptional circumstances?				YES		NO	√			
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None																
Is The Above A Defect Which Is Of Immediate Danger To Persons										YES				NO	√	
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)										NO		√	YES			By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None																
** Visual And Dimension Check was Carried Out.																
Is This Equipment Safe To Operate?										Yes Accept		√	NO Reject			

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Abdullah		Ashraf Alsaad	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.