

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25179-15
Location:	SLICK LINE WORKSHOP	Job Order No:	QC-SLB-25179
Date of Examination:	08/Jul/2025	Next Inspection Due:	07/Jan/2026
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE 11-2022	

IDENTIFICATION NO	DESCRIPTION										QTY	SWL
12261774	<u>Flat 100% Polyester Webbing Sling.</u>										01	Vertical 3000 kg Choker 2400 kg Basket 6000 kg
	<u>Type:</u> EYE X EYE <u>Length:</u> 3M <u>Colour :</u> Yellow <u>Manufacturer:</u> TOHO <u>Safety Factor:</u> 7:1 											
Applicable Reference Standard:		BS EN 1492-1:2000+A1:2008										
* Is this the first examination after installation or assembly at a new site or location?						Was the examination carried out?						
		YES		NO	√	* Within an interval of 6 months?		YES	√	NO		
* If the answer to the above question is YES has the equipment been installed correctly?						* Within an interval of 12 months?		YES		NO	√	
		YES	√	NO		* By an examination scheme?		YES	√	NO		
						* After the occurrence of exceptional circumstances?		YES		NO	√	
		Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None										
Is The Above A Defect Which Is Of Immediate Danger To Persons								YES		NO	√	
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)					NO	√	YES		By:			
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None												
** Visual And Dimension Check was Carried Out.												
Is This Equipment Safe To Operate?					Yes Accept		√	NO Reject				

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammad Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.