


LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25177-17
Location:	WIRE LINE GUN SHOP	Job Order No:	QC-SLB-25177
Date of Examination:	03/Jul/2025	Next Inspection Due:	02/Jan/2026
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
NV93D NV1112A E299D	Safety pin bow Shackles Size: 5/8" Grade: 6 Manufacturer: Crosby 	03	3.25 TON
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	YES	NO	√
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√
	YES	NO	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons	YES	NO	√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)	NO	√	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?	Yes Accept	√	NO Reject

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.