

CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:		QC-SLB/25181-18A		
LOCATION:	WIRE LINE WORKSHOP	JOB NO:		QC-SLB/25181		
EXAMINATION DATE:	12/Jul/2025	LAST INSPECTION		NEXT INSPECTION DATE		
14/Jan/2025		11/Jan/2026		15/JUN/2023		
Serial Number:	QTY	Description				SWL
L-690465-275	01	BOP FRAME Dim: 1.40 M(L) X 0.43 M (W) X 0.87 M (H) FULLY WELDED STEEL CONSTRUCTION WITH FOUR TOP-MOUNTED LIFTING POINTS TARE WEIGHT: 125 kg MAX. GROSS WEIGHT: 815 kg				690 kg
Reference Standard:		BS 7072 (UNIT) # 049				
Pad Eyes Dimension:	Thickness:	Pin Hole:	Length:	Height:	SWL	
	10mm	19mm	50mm	90mm	2 Ton	
Is this the first examination after Installation or assembly at a new site or location?		YES	NO	Was the examination carried out? Within an interval of 6 months? Within an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?		
If the answer to the above question is YES has the equipment been installed correctly?		YES	NO	YES N/A		
Identify any part found to have a defect, which is or could not become a danger to persons, and describe the defect. NONE						
Is the above a defect, which is of immediate danger to persons?						YES
Is the above a defect, which is not yet but could become a danger to persons?						YES by:
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:						
Particulars of any tests carried out as part of the examination: NONE						
** The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory						
** MPI was carried out on the pad eyes Welding Areas and found satisfactory, Check MPI Certificate attached.						
IS THIS EQUIPMENT SAFE TO OPERATE?						YES

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammad Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.