



Al Takamul Company for Engineering Services
Quality Control – Iraq

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25167-23
Location:	FRAC - Workshop	Job Order No:	QC-SLB-25167
Date of Examination:	20/Jun/2025	Next Inspection Due:	19/Dec/2025
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE 04/2024	

IDENTIFICATION NO	DESCRIPTION					QTY	SWL			
24GY2324WM0369	<u>Flat 100% Polyester Webbing Sling.</u> <u>Type</u> : EYE X EYE <u>Length</u>: 10M <u>Colour</u> : Orange <u>Manufacturer</u>: Supertex <u>Safety Factor</u>: 7:1					01	Vertical 10000 kg Choker 8000 Kg Basket 20000 kg			
										
Applicable Reference Standard:		BS EN 1492-1:2000+A1:2008								
* Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?					
	YES		NO	√	* Within an interval of 6 months?		YES	√	NO	
* If the answer to the above question is YES has the equipment been installed correctly?					* Within an interval of 12 months?		YES		NO	√
	YES	√	NO		* By an examination scheme?		YES	√	NO	
				* After the occurrence of exceptional circumstances?		YES		NO	√	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None										
Is The Above A Defect Which Is Of Immediate Danger To Persons						YES			NO	√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)					NO		√	YES		By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None										
** Visual And Dimension Check was Carried Out.										
Is This Equipment Safe To Operate?					Yes Accept		√	NO Reject		

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
M-TAREK		Ashraf Elsaad	



THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

