



Al Takamul Company for Engineering Services
Quality Control – Iraq

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25167-23
Location:	FRAC - Workshop	Job Order No:	QC-SLB-25167
Date of Examination:	20/Jun/2025	Next Inspection Due:	19/Dec/2025
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE 04/2024	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
C5139 C5153	<u>Flat 100% Polyester Webbing Sling.</u> Type : EYE X EYE Length: 6M Colour : Red Manufacturer: Sasty Marine Services Safety Factor: 7:1	02	Vertical 5 Tone Choker 4 Tone Basket 8 Tone
Applicable Reference Standard:	BS EN 1492-1:2000+A1:2008		
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?		
	YES	NO	✓
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?		
	YES	NO	✓
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 12 months?		
	YES	NO	✓
* If the answer to the above question is YES has the equipment been installed correctly?	* By an examination scheme?		
	YES	NO	✓
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?			
Yes Accept			
NO Reject			

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
M-TAREK		Ashraf Elsaad	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

