


LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB - BASRA	Certificate no:	QC-SLB-25186/25
Location:	MAST # 2 TEAM#2	Job Order No:	QC-SLB-25186
Date of Examination:	15-Jul-2025	Next Inspection Due:	14- Jan -2026
Last Inspection		Last Proof Load Test Date	
N/A		By Manufacture	

IDENTIFICATION NO	DESCRIPTION										QTY	SWL
M15	Safety pin bow Shackles Size: 3/4” Manufacture: CROSBY Grade: 6 Safety Factor: 6:1 Location: Cement Block 										01	4.75 TON
Applicable Reference Standard:		BS EN 13889 :2003+A2:2008										
* Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?							
	YES		NO	√	* Within an interval of 6 months?		YES	√	NO			
* If the answer to the above question is YES has the equipment been installed correctly?					* Within an interval of 12 months?		YES		NO	√		
	YES	√	NO		* By an examination scheme?		YES	√	NO			
					* After the occurrence of exceptional circumstances?		YES		NO	√		
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None												
Is The Above A Defect Which Is Of Immediate Danger To Persons							YES		NO	√		
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)					NO	√	YES		By:			
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None												
** Visual And Dimension Check was Carried Out.												
Is This Equipment Safe To Operate?					Yes Accept		√	NO Reject				

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Tarek		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.