

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATION NO:	QC-SLB-25184-026
LOCATION:	TESTING	JOB NO:	QC-SLB-25184
EXAMINATION DATE:	16/Jul/2025		
LAST INSPECTION	NEXT INSPECTION DATE	LAST PROOF LOAD TEST DATE	
N/A	15/Jan/2026	BY MANUFACTURE	
IDENTIFICATION NO	DESCRIPTION	QTY	SWL
10952528	WEBBING SLING Manufacture: GS Date of Manufacture: 14-2011 Material: Polyester Effective Length: 4 m Straight Pull: 10 TON Basket Hitch: 20 TON Choker Hitch: 8 TON Safety Factor: 7:1	01	10 TON
Applicable Reference Standard:	BS EN 1492-1:2000+A1:2008		
* Is this the first examination after installation or assembly at a new site or location?	YES ☐ NO ☒	Was the examination carried out?	
		Within an interval of 6 months?	
		YES ☒	NO ☐
* If the answer to the above question is YES has the equipment been installed correctly?	YES ☒ NO ☐	* Within an interval of 12 months?	
		YES ☐	NO ☒
		* By an examination scheme?	
		YES ☒	NO ☐
		* After the occurrence of exceptional circumstances?	
		YES ☐	NO ☒
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES ☐	NO ☒
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO ☒	YES ☐
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept ☒	NO Reject ☐

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammed Abdallah		Ashraf Alsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.