

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB-25179-32			
LOCATION:	SLICKLINE WORKSHOP					
EXAMINATION DATE:	08/Jul/2025	JOB NO:	QC-SLB-25179			
LAST INSPECTION		NEXT INSPECTION DATE		PROOF LOAD TEST DATE		
12/Jan/2025		07/Jan/2026		By Manufacture		
IDENTIFICATION NO	DESCRIPTION			QTY		
100341-9/74	Flat 100% Polyester Webbing Sling. Type: Eye x Eye Length: 6 meter Color: Yellow Manufacturer: LIFTEK Safety Factor: 7:1			01		
						
Applicable Reference Standard:		BS EN 1492-1:2000+A1:2008 UNIT #03				
* Is this the first examination after installation or assembly at a new site or location? * If the answer to the above question is YES has the equipment been installed correctly?		Was the examination carried out?				
		YES	NO	✓		
		* Within an interval of 6 months?		YES	✓	NO
		* Within an interval of 12 months?		YES	NO	✓
YES		✓	NO			
* By an examination scheme?		YES	✓	NO		
* After the occurrence of exceptional circumstances?		YES	NO	✓		
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None						
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO	✓		
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	✓	YES		
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None						
** Visual And Dimension Checks was Carried Out.						
Is This Equipment Safe To Operate?		Yes Accept	✓	NO Reject		

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammad Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

