



Al Takamul Company for Engineering Services
Quality Control – Iraq

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB - BASRA	Certificate no:	QC-SLB-25186/34
Location:	MAST # 2 TEAM#2	Job Order No:	QC-SLB-25186
Date of Examination:	15-Jul-2025	Next Inspection Due:	14- Jan -2026
Last Inspection		Last Proof Load Test Date	
N/A		By Manufacture	

IDENTIFICATION NO	DESCRIPTION						QTY	SWL		
WG1421 WG1607	ROUND SLING (F.S.R) Manufacture: GRIPTION Manufacture Date: 05/12/2018 Length: 4 m Safety Factor: 7:1 Colour: Grey 						02	Vertical 4000 kg Checker 3200 Kg Basket 8000 kg		
Applicable Reference Standard:	EN 1492-2: 2000+A1:2008									
* Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?					
	YES		NO	✓	* Within an interval of 6 months?		YES	✓	NO	
					* Within an interval of 12 months?		YES		NO	✓
* If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO		* By an examination scheme?		YES	✓	NO	
					* After the occurrence of exceptional circumstances?		YES		NO	✓
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None										
Is The Above A Defect Which Is Of Immediate Danger To Persons							YES		NO	✓
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)					NO	✓	YES		By:	
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None										
** Visual And Dimension Check was Carried Out.										
Is This Equipment Safe To Operate?					Yes Accept		✓	NO Reject		

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Tarek		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.