



Al Takamul Company for Engineering
Services
Quality Control – Iraq

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25192-34
Location:	WIRE LINE WORKSHOP	Job Order No:	QC-SLB-25192
Date of Examination:	23/July/2025	Next Inspection Due:	22/Jan/2026
Last Inspection		Last Proof Load Test Date	
12/Jan/2025		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION		QTY	SWL
HST-027014-100	<u>ROUND WEBBING SLING FOR LOGIN UNIT RIG UP</u> Material :POLYSTER Length : 16 ft Manufacturer : FARGAMEL Safety Factor: 7:1 FISHING KIT # 03		01	VERTICAL: 50,000 LBS CHOKER: 40,000 LBS BASKET: 86.600 LBS
Applicable Reference Standard:	BS EN 1492-1:2000+A1:2008			
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	NO	✓	
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?			
	YES	NO	✓	
	* Within an interval of 12 months?			
	YES	NO	✓	
	* By an examination scheme?			
	YES	NO	✓	
	* After the occurrence of exceptional circumstances?			
	YES	NO	✓	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None				
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None				
** Visual And Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept	✓	NO Reject

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Abdullah		Ashraf Alsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

