


LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB Basra (Testing)	CERTIFICATE NO:	QC-SLB/25184-37
LOCATION:	Testing Work Shop	JOB NO:	QC-SLB/25184
EXAMINATION DATE:	20/Jul/2025		
LAST INSPECTION	NEXT INSPECTION DATE	LAST PROOF LOAD TEST DATE	
N/A	19/Jan/2026	BY MANUFACTURE	
IDENTIFICATION NO	DESCRIPTION	QTY	SWL
BG42 H1500	Safety pin bow Shackle Size: 7/8" Grade: 6 Safety Factor: 6:1 Manufacturer: CROSBY	02	6.5 TON
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	✓
* If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO
Was the examination carried out?	Within an interval of 6 months? YES ✓ NO * Within an interval of 12 months? YES NO ✓ * By an examination scheme? YES ✓ NO * After the occurrence of exceptional circumstances? YES NO ✓		
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons	YES	NO	✓
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)	NO	✓	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?	Yes Accept	✓	NO Reject
INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammed Abdallah		ASHRAF ELSAID	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

