



Al Takamul Company for Engineering Services
Quality Control – Iraq


LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB/25210-02A
Location:	D&M YARD	Job Order No:	QC-SLB/25210
Date of Examination:	11-Aug-2025	Next Inspection Due:	10-Feb-2026
Last Inspection		Last Proof Load Test Date	
		After Any Repair Or Modification	

Serial Number:	QTY	Description	PAYLOAD
1010577	01	<u>MUD LOGGING UNIT</u> FULLY WELDED STEEL CONSTRUCTION WITH FOUR TOP-MOUNTED LIFTING POINTS. Dimension: 8.26 m(L) X 2.43 m (W) X 2.54 m (H) Tare weight: 7400 KG Max Gross weight: 10000 KG	2500 KG

Reference Standard:	DNV2.7-1 & 2.7-2			
Pad Eyes Dimension:	Thickness:	Pin Hole:	Length:	Height:
	34 mm	30 mm	160 mm	105 mm



Is this the first examination after Installation or assembly at a new site or location?	YES		NO	✓	Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES	✓	NO	
						YES		NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO			YES	✓	NO	
				N/A		YES		NO	✓

Identification of any part found to have a defect, which is or could not become a danger to persons, and a description of the defect.

NONE

Is the above a defect, which is of immediate danger to persons? YES NO ✓

Is the above a defect, which is not yet but could become a danger to persons? YES by:

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: **NONE**

** The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

** MPI was carried out on the pad eyes Welding Areas and found satisfactory, Check MPI Certificate No : (.....) attached.

IS THIS EQUIPMENT SAFE TO OPERATE? YES ✓ NO

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammad Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT: a competent person on behalf of the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection. And considered safe for Lifting.

