

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB Basra (MI SWACO)	Certificate no:	QC-SLB/25197-03
Location:	Rig HH-30	Job Order No:	QC-SLB/25197
Date of Examination:	10-Aug-2025	Next Inspection Due:	09-Feb-2026
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION		QTY	SWL
B13-5702	<u>Four Leg Wire Rope Sling.</u> Dim: 20 mm (Dia) X 4.0m (L) IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE C/W MASTER LINK ASSEMBLY AT TOP HARD EYE BOTH END SAFETY FACTOR 5:1		01	9.6 TON AT 0-45 DEG
Applicable Reference Standard:		BS EN 13414-1:2003+A2:2008		
* Is this the first examination after installation or assembly at a new site or location?		Was the examination carried out?		
		YES	NO	✓
* If the answer to the above question is YES has the equipment been installed correctly?		* Within an interval of 6 months?		
		YES	NO	✓
		* Within an interval of 12 months?		
		YES	NO	✓
		* By an examination scheme?		
		YES	NO	✓
		* After the occurrence of exceptional circumstances?		
		YES	NO	✓
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None				
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES	NO ✓
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO ✓	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None				
** Visual And Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept	✓	NO Reject

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohamed Abdalla		Ashraf Elsaid	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.