



Al Takamul Company for Engineering Services
Quality Control – Iraq

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25206-05
Location:	WIRE LINE WORKSHOP	Job Order No:	QC-SLB-25206
Date of Examination:	8/Aug/2025	Next Inspection Due:	7/Fab/2026
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE 11/24	

IDENTIFICATION NO	DESCRIPTION		QTY	SWL
54750089	Flat 100% Polyester Webbing Sling. Type: EYE X EYE Length: 2 Meter Color: Yellow Manufacturer: DELTAPLUS Safety Factor: 7:1		01	Vertical 3000 KG Chocker 2400 KG Basket 6000 KG
Applicable Reference Standard:		BS EN 13155		
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	✓	NO	
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?			
	YES	✓	NO	✓
	* Within an interval of 12 months?			
	YES	✓	NO	✓
	* By an examination scheme?			
	YES	✓	NO	✓
	* After the occurrence of exceptional circumstances?			
	YES	✓	NO	✓
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None				
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES	NO ✓
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO ✓	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None				
** Visual and Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept	✓	NO Reject

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Abdullah		Ashraf Alsaad	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.