

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB-25209-115	
LOCATION:	ARTIFICIAL LIFT			
EXAMINATION DATE:	24/Aug/2025		JOB NO:	QC-SLB-25209
LAST INSPECTION		NEXT INSPECTION DATE		LAST PROOF LOAD TEST DATE
24/Feb/2025		23/Feb/2026		BY MANUFACTURE
IDENTIFICATION NO	DESCRIPTION			QTY
LG199095-260	<u>Single Leg Chain Sling.</u> Dim: 10mm X 4ft C/W Grab Connector At The End G 80 SAFETY FACTOR 4:1			01
				
Applicable Reference Standard:		BS EN 818-2:1996+A1:2008		
* Is this the first examination after installation or assembly at a new site or location?	YES		NO	✓
	YES		✓	NO
	YES		✓	NO
* If the answer to the above question is YES has the equipment been installed correctly?	YES		✓	NO
	YES		✓	NO
	YES		✓	NO
Identification of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and A Description of the Defect: None				
Is The Above a Defect Which Is of Immediate Danger to Persons		YES		NO
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State The Date By When)		NO	✓	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None				
** Visual and Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept	✓	NO Reject

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammed Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

