Al TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED
Basra, North Rumaila, Quality Control Yard - Iraq

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	**SLB BASRA**	**CERTIFICATE NO:**	**QC-SLB-25209-120**	
LOCATION:	**ARTIFICIAL LIFT**			
EXAMINATION DATE:	**24/Aug/2025**	**JOB NO:**	**QC-SLB-25209**	

LAST INSPECTION	NEXT INSPECTION DATE	LAST PROOF LOAD TEST DATE
24/Feb/2025	23/Feb/2026	BY MANUFACTURE

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
110-94	**Safety pin bow Shackles** **Size: 1''** **Grade: 6** **Manufacturer: Bash-P** **Safety Factor: 6:1** 	**01**	**8.5TON**

Applicable Reference Standard:	**BS EN 13889 / US FED SPEC RR-C-27 1 D**							
*** Is this the first examination after installation or assembly at a new site or location?**	YES		NO	√	**Was the examination carried out?**			
					*** Within an interval of 6 months?**	YES	√	NO
					*** Within an interval of 12 months?**	YES		NO √
*** If the answer to the above question is YES has the equipment been installed correctly?**	YES	√	NO		*** By an examination scheme?**	YES	√	NO
					*** After the occurrence of exceptional circumstances?**	YES		NO √

Identification of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and A Description of the Defect: **None**

Is The Above a Defect Which Is of Immediate Danger to Persons			**YES**		**NO**	√
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State The Date By When)	**NO**	√	**YES**		**By:**	

Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: **None**

**** Visual and Dimension Check was Carried Out.**

Is This Equipment Safe To Operate?	**Yes Accept**	√	**NO Reject**	

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammed Abdullah		**Ashraf Elsaad**	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.