




Al Takamul Company for Engineering Services
Quality Control – Iraq

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25198 -13
Location:	COIL TUBING WORK SHOP	Job Order No:	QC-SLB-25198
Date of Examination:	22/Aug/2025	Next Inspection Due:	21/Feb/2026
Last Inspection		Last Proof Load Test Date	
N/A		AFTER ANY REPAIR OR MODIFICATION	

IDENTIFICATION NO	DESCRIPTION										QTY	SWL		
A206	Safety pin bow Shackles Size: 1 1/4” Grade: 6 Safety Factor: 6:1 Manufacturer: MCL 										01	12 TON		
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D													
* Is this the first examination after installation or assembly at a new site or location?	YES				NO				Was the examination carried out?					
									* Within an interval of 6 months?		YES	√	NO	
									* Within an interval of 12 months?		YES		NO	√
* If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		* In accordance with an examination scheme?		YES	√	NO					
					* After the occurrence of exceptional circumstances?		YES		NO	√				
Identification of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and a Description of the Defect: None														
Is The Above a Defect Which Is of Immediate Danger to Persons								YES				NO	√	
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State the Date by When)						NO		√	YES				By:	
Particulars Of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above: None														
** Visual and Dimension Check was Carried Out.														
Is This Equipment Safe to Operate?					Yes Accept			√		NO Reject				

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Abdallah		Ashraf El-saad	

THIS IS TO CERTIFY THAT: a competent person has examined the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection, And considered Safe for Lifting.

