

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB-25209-151
LOCATION:	ARTIFICIAL LIFT	JOB NO:	QC-SLB-25209
EXAMINATION DATE:	24/Aug/2025		
LAST INSPECTION	NEXT INSPECTION DATE	LAST PROOF LOAD TEST DATE	
24/Feb/2025	23/Feb/2026	BY MANUFACTURE	
IDENTIFICATION NO	DESCRIPTION	QTY	SWL
Z1489	FLAT WEBBING SLING Material: Polyester Length: 8M Manufacturer: Safety Marine Services Colour: Orange Safety Factor: 7:1	01	VERTICAL: 6 TON CHOKER: 4800 KGS BASKET: 12 TON
Applicable Reference Standard:	BS EN 1492-1:2000+A1:2008		
* Is this the first examination after installation or assembly at a new site or location? * If the answer to the above question is YES has the equipment been installed correctly?	Was the examination carried out? YES ☒ NO ☒		
	* Within an interval of 6 months? YES ☒ NO ☒		
	* Within an interval of 12 months? YES ☒ NO ☒		
	* By an examination scheme? YES ☒ NO ☒		
* After the occurrence of exceptional circumstances? YES ☒ NO ☒			
Identification of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES ☒	NO ☒
Is The Above a Defect Which Is Not Yet but Could Become a Danger To Persons: (If YES State The Date By When)		NO ☒	YES ☒
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual and Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept ☒	NO Reject ☒

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammed Abdallah		ASHRAF ELSAID	

THIS IS TO CERTIFY THAT; a competent person did examine the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

