

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB-25209-158																				
LOCATION:	ARTIFICIAL LIFT	JOB NO:	QC-SLB-25209																				
EXAMINATION DATE:	24/Aug/2025																						
LAST INSPECTION	NEXT INSPECTION DATE	LAST PROOF LOAD TEST DATE																					
24/Feb/2025	23/Feb/2026	BY MANUFACTURE																					
IDENTIFICATION NO	DESCRIPTION	QTY	SWL																				
A9368	<u>Four Leg Wire Rope Sling.</u> Dim: 26mm X 6m IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE C/W MASTER LINK ASSEMBLY AT TOP HARD EYE X SOFT EYE SAFETY FACTOR 5:1 	01	18 Ton @0-45°																				
Applicable Reference Standard:	BS EN 13414-1:2003+A2:2008																						
* Is this the first examination after installation or assembly at a new site or location?	<table border="1"> <tr> <td>YES</td> <td></td> <td>NO</td> <td>√</td> </tr> </table>			YES		NO	√																
YES		NO	√																				
* If the answer to the above question is YES has the equipment been installed correctly?	<table border="1"> <tr> <td>YES</td> <td>√</td> <td>NO</td> <td></td> </tr> </table>			YES	√	NO																	
YES	√	NO																					
	<table border="1"> <tr> <td colspan="2">Was the examination carried out?</td> <td colspan="2"></td> </tr> <tr> <td>* Within an interval of 6 months?</td> <td>YES</td> <td>√</td> <td>NO</td> </tr> <tr> <td>* Within an interval of 12 months?</td> <td>YES</td> <td></td> <td>NO</td> </tr> <tr> <td>* In accordance with an examination scheme?</td> <td>YES</td> <td>√</td> <td>NO</td> </tr> <tr> <td>* After the occurrence of exceptional circumstances?</td> <td>YES</td> <td></td> <td>NO</td> </tr> </table>			Was the examination carried out?				* Within an interval of 6 months?	YES	√	NO	* Within an interval of 12 months?	YES		NO	* In accordance with an examination scheme?	YES	√	NO	* After the occurrence of exceptional circumstances?	YES		NO
Was the examination carried out?																							
* Within an interval of 6 months?	YES	√	NO																				
* Within an interval of 12 months?	YES		NO																				
* In accordance with an examination scheme?	YES	√	NO																				
* After the occurrence of exceptional circumstances?	YES		NO																				
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None																							
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO																				
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	YES																				
Particulars Of Any Repair, Renewal Or Alteration Required To Remedy The Defect Identified Above: None																							
** Visual And Dimension Check was Carried Out.																							
Is This Equipment Safe To Operate?		Yes Accept	NO Reject																				

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammed Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

