



LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25198 -16
Location:	COIL TUBING WORK SHOP	Job Order No:	QC-SLB-25198
Date of Examination:	22/Aug/2025	Next Inspection Due:	21/Feb/2026
Last Inspection		Last Proof Load Test Date	
N/A		AFTER ANY REPAIR OR MODIFICATION	

IDENTIFICATION NO	DESCRIPTION										QTY	SWL	
P145C	Safety pin bow Shackles Size: 1 '' Grade: 6 Safety Factor: 6:1 Manufacturer: GT 										01	8.5 TON	
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D												
* Is this the first examination after installation or assembly at a new site or location?	YES					NO	√	Was the examination carried out?					
							* Within an interval of 6 months?		YES	√	NO		
							* Within an interval of 12 months?		YES		NO	√	
* If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		* In accordance with an examination scheme?			YES	√	NO			
					* After the occurrence of exceptional circumstances?			YES		NO	√		
Identification of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and a Description of the Defect: None													
Is The Above a Defect Which Is of Immediate Danger to Persons								YES			NO		√
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State the Date by When)								NO		√	YES		By:
Particulars Of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above: None													
** Visual and Dimension Check was Carried Out.													
Is This Equipment Safe to Operate?								Yes Accept		√	NO Reject		

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Abdallah		Ashraf El-saad	

THIS IS TO CERTIFY THAT: a competent person has examined the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection, And considered Safe for Lifting.

