

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB-25209-161
LOCATION:	ARTIFICIAL LIFT	JOB NO:	QC-SLB-25209
EXAMINATION DATE:	24/Aug/2025		
LAST INSPECTION	NEXT INSPECTION DATE	PROOF LOAD TEST DATE	
24/Feb/2025	23/Feb/2026	BY MANUFACTURE	
IDENTIFICATION NO	DESCRIPTION	QTY	SWL
KIM-OS-12-093	<u>CENTER HOOK</u> MANUFACTURE: KTL OFFSHORE DIA: 4 1/2" , 2 7/8" , 2 3/8"	01	12000 LBS
Applicable Reference Standard:	EN 1677-4		
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?		
	YES	NO	√
	* Within an interval of 6 months?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES		
	YES	NO	√
	* By an examination scheme?		
YES			√
* After the occurrence of exceptional circumstances?			YES
YES			NO
Identification of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and A Description of the Defect: None			
Is The Above a Defect Which Is of Immediate Danger to Persons			YES
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State The Date By When)			NO
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			By:
** Visual and Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammed Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

