

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB-25209-175	
LOCATION:	ARTIFICIAL LIFT			
EXAMINATION DATE:	24/Aug/2025	JOB NO:	QC-SLB-25209	
LAST INSPECTION	NEXT INSPECTION DATE	LAST PROOF LOAD TEST DATE		
24/Feb/2025	23/Feb/2026	BY MANUFACTURE		
IDENTIFICATION NO	DESCRIPTION		QTY	SWL
SC1062 SC8496 SC8380	<u>LIFTING CLAMP ASSEMBLY</u> Lifting Clamp Assembly, Into Two Halves Bolted Together Complete of Two Lifting Points One On Each Side. Constructed of Welded Steel Plates. Manufacture: SCIMEX PRECISION ENGINEERING		03	12300 LBS
Applicable Reference Standard:	BS EN 13155			
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√	
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√	
		Was the examination carried out?		
		* Within an interval of 6 months?		
		YES		
		√		
		NO		
		√		
		* Within an interval of 12 months?		
		YES		
		√		
		NO		
		√		
		* By an examination scheme?		
		YES		
		√		
		NO		
		√		
		* After the occurrence of exceptional circumstances?		
		YES		
		√		
		NO		
		√		
Identification of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and A Description of the Defect: None				
Is The Above a Defect Which Is of Immediate Danger to Persons		YES	NO	√
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons:		NO	√	YES
(If YES State The Date By When)				By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None				
** Visual and Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept	√	NO Reject

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammed Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person has examined the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.