

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB/25247-06	
LOCATION:	Compilation Workshop			
EXAMINATION DATE:	27/Sep/2025	JOB NO:	QC-SLB/25247	
LAST INSPECTION	NEXT INSPECTION DATE		LAST PROOF LOAD TEST DATE	
N/A	26/Mar/2026		BY MANUFACTURE	
IDENTIFICATION NO	DESCRIPTION		QTY	WLL
1998/1	<u>Five Leg Wire Rope Sling.</u> Top Leg: Dim: 32 mm (Día) X 1.50m (L) Bottom Leg: Dim:22mm (Dia) X 4 (L) IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE C/W MASTER LINK ASSEMBLY AT TOP HARD EYE AT BOTH END SAFETY FACTOR 5:1 		01	13 TON AT 0-45 DEG
Applicable Reference Standard:	BS EN 13414-1:2003+A2:2008			
* Is this the first examination after installation or assembly at a new site or location? * If the answer to the above question is YES has the equipment been installed correctly?	Was the examination carried out?			
	YES		NO	√
	* Within an interval of 6 months?		YES	√
	* Within an interval of 12 months?		YES	NO
YES	√	NO		
* By an examination scheme?		YES	√	NO
* After the occurrence of exceptional circumstances?		YES		NO
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None				
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES		NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	√	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None				
** Visual And Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept	√	NO Reject

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohamed Abdallah		Ashraf Alsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

