


LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB/25241-09
LOCATION:	Compilation Workshop	JOB NO:	QC-SLB/25241
EXAMINATION DATE:	20/Sep/2025		
LAST INSPECTION	N/A	NEXT INSPECTION DATE	19/Mar/2026
		LAST PROOF LOAD TEST DATE	BY MANUFACTURE
IDENTIFICATION NO	DESCRIPTION		QTY
05 06 07 08	Safety pin bow Shackles SIZE: 1-3/8" Grade: 6 Manufacturer: MT Safety Factor: 6:1		04
			
		13.5 TON	
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D		
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?		
	YES	NO	√
	* Within an interval of 6 months?		YES
	YES	NO	√
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 12 months?		YES
	YES	NO	√
	* By an examination scheme?		YES
	YES	NO	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons:		NO	YES
(If YES State The Date By When)		√	By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?	Yes Accept	√	NO Reject

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohamed Abdallah		Ashraf Alsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

