


LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB-25218-14	
LOCATION:	TESTING Workshop			
EXAMINATION DATE:	11/Sep/2025	JOB NO:	QC-SLB-25218	
LAST INSPECTION		NEXT INSPECTION DATE		LAST PROOF LOAD TEST DATE
8/Apr/2025		10/Mar/2026		BY MANUFACTURE
IDENTIFICATION NO	DESCRIPTION		QTY	SWL
B04 58124 AF01 P620	<u>Safety pin bow Shackles</u> Size: 7/8" Grade: 6 Manufacturer: Crosby, Toyolift, J&L, GP Safety Factor: 6:1 		04	6.5TON
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D			
* Is this the first examination after installation or assembly at a new site or location?	YES		NO	
	YES		NO	
* If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	
	YES		NO	
Identification of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and A Description of the Defect: None				
Is The Above a Defect Which Is of Immediate Danger to Persons		YES		NO
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State The Date By When)		NO		YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None				
** Visual and Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept		NO Reject
INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:	
Mohammed Abdullah		Ashraf Elsaad		

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.