



VISUAL THOROUGH EXAMINATION

Client:	SLB – Basra	Certificate no:	QC-SLB/25216-15
Location:	Coiltubing Work Shop	Job Order No:	QC-SLB/25216
Date of Examination:	23-Aug-2025	Next Inspection Due:	22-Feb-2026
Last Inspection		Last Test Date	
N/A		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION	QTY	Max Pressure Rating
2208663-22 2208663-102 2208663-91 2208663-43 2208663-28	Flow Line Safety Restraint (FSR) Material: Nylon Length: 04 ft Colour : Red Manufacturer: SPM  Note: Flow Line Safety Restraint (FSR) system is designed to help contain high-pressure piping and components in case of rupture during the pumping process. so it's not for lifting.	05	15000 PSI
Applicable Reference Standard:	Manufacture Document: 2P37221		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	✓
	YES	NO	✓
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	✓
	YES	NO	✓
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Abdullah		Ashraf Alsaad	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.