


LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25218-15
Location:	TESTING Workshop	Job Order No:	QC-SLB-25218
Date of Examination:	11/Sep/2025	Next Inspection Due:	10/Mar/2026
Last Inspection		Last Proof Load Test Date	
8/Apr/2025		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION										QTY	SWL
SC9 (TS-14)	<u>Four Leg Wire Rope Sling.</u> Dim: 22 mm (Día) X 2.75 m (L) IWRC, MECHANICALLY SPLICED WITH STEEL FERRULE C/W MASTER LINK ASSEMBLY AT TOP HARD EYE BOTH END SAFETY FACTOR 5:1 										01	9.6TON @45°
Applicable Reference Standard:	BS EN 13414-1:2003+A2:2008											
* Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?							
	YES		NO	√	Within an interval of 6 months? *		YES	√	NO			
					* Within an interval of 12 months?		YES		NO	√		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		* In accordance with an examination scheme?		YES	√	NO			
					* After the occurrence of exceptional circumstances?		YES		NO	√		
Identification of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and A Description of the Defect: None												
Is The Above a Defect Which Is of Immediate Danger to Persons							YES		NO	√		
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State The Date By When)					NO	√	YES		By:			
Particulars Of Any Repair, Renewal Or Alteration Required To Remedy The Defect Identified Above: None												
** Visual and Dimension Check was Carried Out.												
Is This Equipment Safe To Operate?					Yes Accept		√	NO Reject				

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Abdullah		Ashraf El-saad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.