

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB-25231-18
LOCATION:	ARTIFICIAL LIFT		
EXAMINATION DATE:	16/Sep/2025	JOB NO:	QC-SLB-25231
LAST INSPECTION	NEXT INSPECTION DATE	LAST PROOF LOAD TEST DATE	
N/A	15/Mar/2026	BY MANUFACTURE	
IDENTIFICATION NO	DESCRIPTION		QTY
6224	<u>Textile Round Webbing Sling.</u> Material: Nylon Length: 4M Color: Greey Manufacturer: Safety Marine Safety Factor:7:1 		01
	VERTICAL: 4 TON CHOKER: 3200 KGS BASKET: 8 TON		
Applicable Reference Standard:	BS EN 1492-1:2000+A1:2008		
* Is this the first examination after installation or assembly at a new site or location? * If the answer to the above question is YES has the equipment been installed correctly?	Was the examination carried out? * Within an interval of 6 months? YES ☒ NO ☐ * Within an interval of 12 months? YES ☐ NO ☒ * By an examination scheme? YES ☒ NO ☐ * After the occurrence of exceptional circumstances? YES ☐ NO ☒		
	Identification of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and A Description of the Defect: None		
	Is The Above a Defect Which Is of Immediate Danger to Persons YES ☐ NO ☒ Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: NO ☒ YES ☐ By: (If YES State The Date By When)		
Particulars of Any Repair, Renewal, Or Alteration Required to Remedy the Defect Identified Above: None			
** Visual and Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?	Yes Accept	☒	NO Reject ☐

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammed Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

