

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB-25245-22
LOCATION:	ARTIFICIAL LIFT	JOB NO:	QC-SLB-25245
EXAMINATION DATE:	23/Sep/2025	LAST INSPECTION	24/Feb/2025
NEXT INSPECTION DATE	22/Mar/2026	LAST PROOF LOAD TEST DATE	BY MANUFACTURE
IDENTIFICATION NO	DESCRIPTION		QTY
F4621-8	CENTER HOOK MANUFACTURE: KTL OFFSHORE DIA: 7 7/8" , 7 1/2" , 7 1/8" , 6 3/4" , 6 1/2"		01
SWL	24000 LBS		
Applicable Reference Standard:	EN 1677-4		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	✓
* If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO
Was the examination carried out?	* Within an interval of 6 months? YES ✓ NO * Within an interval of 12 months? YES NO ✓ * By an examination scheme? YES ✓ NO * After the occurrence of exceptional circumstances? YES NO ✓		
Identification of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and A Description of the Defect: None			
Is The Above a Defect Which Is of Immediate Danger to Persons	YES	NO	✓
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State The Date By When)	NO	✓	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual and Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?	Yes Accept	✓	NO Reject

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammed Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.