


LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB/25239-24	
LOCATION:	WIRE LINE WORKSHOP			
EXAMINATION DATE:	28/Sep/2025		JOB NO:	QC-SLB/25239
LAST INSPECTION		NEXT INSPECTION DATE		LAST PROOF LOAD TEST DATE
N/A		27/Mar/2026		BY MANUFACTURE
IDENTIFICATION NO	DESCRIPTION			QTY
NE3345A NE3345B NE3345C NE3345D	Safety pin bow Shackles SIZE: 1/2" Grade: 6 Manufacturer: Crosby Safety Factor: 6:1 			04
SWL 2 TON				
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D			
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	NO	YES	NO
	YES	NO	YES	NO
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?			
	YES	NO	YES	NO
	YES	NO	YES	NO
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None				
Is The Above A Defect Which Is Of Immediate Danger To Persons				YES
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)				NO
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above:				By:
** Visual And Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept	NO Reject	

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohamed Abdallah		Ashraf Alsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

