


LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB-25227-28	
LOCATION:	SLICK LINE WORKSHOP			
EXAMINATION DATE:	05/Sep/2025	JOB NO:	QC-SLB-25227	
LAST INSPECTION		NEXT INSPECTION DATE		LAST PROOF LOAD TEST DATE
06/Mar/2025		04/Mar/2026		By Manufacture
IDENTIFICATION NO	DESCRIPTION			QTY
WAL-11-3812 WAL-11-3811 WAL-11-3810 NV78	Safety pin bow Shackles Size: 1 1/8" Grade: 6 Manufacturer: Crosby Safety Factor : 6:1 			04
				9.5 TON
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D (UNIT # 4)			
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	NO	✓	
	* Within an interval of 6 months?		YES	✓
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 12 months?		YES	✓
	* By an examination scheme?		YES	✓
	* After the occurrence of exceptional circumstances?		YES	✓
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None				
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None				
** Visual And Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept	✓	NO Reject

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohamed Abdallah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

