




LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB – Basra	Certificate no:	QC-SLB/25230-43
Location:	Coil tubing Work Shop	Job Order No:	QC-SLB/252230
Date of Examination:	17-Sep-2025	Next Inspection Due:	16-Mar-2026
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION										QTY	SWL	
111 112	Safety pin bow Shackles <u>Diameter:</u> 1/2" <u>Grade:</u> 6 <u>Manufacturer:</u> CROSBY 										02	2 TON AT 0-45 DEG	
Applicable Reference Standard:		BS EN 13889											
* Is this the first examination after installation or assembly at a new site or location?						Was the examination carried out?							
		YES		NO	√	* Within an interval of 6 months?		YES	√	NO			
						* Within an interval of 12 months?		YES		NO	√		
* If the answer to the above question is YES has the equipment been installed correctly?		YES	√	NO		* By an examination scheme?		YES	√	NO			
						* After the occurrence of exceptional circumstances?		YES		NO	√		
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None													
Is The Above A Defect Which Is Of Immediate Danger To Persons										YES		NO	√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)										NO	√	YES	By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None													
** Visual And Dimension Check was Carried Out.													
Is This Equipment Safe To Operate?										Yes Accept	√	NO Reject	

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Abdullah		Ashraf Alsaad	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.