QUALITY CONTROL	Al Takamul Company for Engineering Services Quality Control – Iraq	

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB – Basra	**Certificate no:**	QC-SLB/25236-43
Location:	Coil Tubing work shop (CTU3 - Team4)	**Job Order No:**	QC-SLB/25236
Date of Examination:	15-Sep-2025	**Next Inspection Due:**	14-Mar-2026
Last Inspection		**Last Proof Load Test Date**	
N/A		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
G8275	**Single Leg Wire Rope Sling.** **DIAMETER: 24 mm** **LENGTH: 1 m** **MANUFACTURER: Safety Marine** **IWRC, MECHANICALLY SPLICED** **WITH STEEL FERRULE** **HARD EYE WITH MASTER LINK ON BOTH ENDS.** **SAFETY FACTOR 5:1** 	**01**	**6.7 TON AT 0-45 DEG**
Applicable Reference Standard:	**BS EN 13414-1:2003+A2:2008**		

					Was the examination carried out?				
*** Is this the first examination after installation or assembly at a new site or location?**	YES		NO	√	*** Within an interval of 6 months?**	YES	√	NO	
					*** Within an interval of 12 months?**	YES		NO	√
*** If the answer to the above question is YES has the equipment been installed correctly?**	YES	√	NO		*** By an examination scheme?**	YES	√	NO	
					*** After the occurrence of exceptional circumstances?**	YES		NO	√

Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: **None**

Is The Above A Defect Which Is Of Immediate Danger To Persons			**YES**		**NO**	√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)	**NO**	√	**YES**		**By:**	

Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: **None**

**** Visual And Dimension Check was Carried Out.**

Is This Equipment Safe To Operate?	**Yes Accept**	√	**NO Reject**	

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohamed Abdullah		**Ashraf Alsaad**	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.