

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB – Basra	Certificate no:	QC-SLB/25236-56
Location:	Coil Tubing work shop (CTU3 - Team4)	Job Order No:	QC-SLB/25236
Date of Examination:	15-Sep-2025	Next Inspection Due:	14-Mar-2026
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION				QTY	SWL
B2460	<u>Five Leg Wire Rope Sling.</u> Top Leg Dim: 36 MM (Dia) X 1.5 M (L) Bottom Leg Dim: 28 MM (Dia) X 2.43 M (L) Manufacturer: SAFETY MARINE IWRC, MECHANICALLY SPliced WITH ALUMINUM FERRULE C/W MASTER LINK ASSEMBLY AT TOP HARD EYE AT BOTH END SAFETY FACTOR 5:1				01	15 TON AT 45-60 DEG 21 TON AT 0-45 DEG
Applicable Reference Standard:		BS EN 13414-1:2003+A2:2008				
* Is this the first examination after installation or assembly at a new site or location?		Was the examination carried out?				
		YES		NO	✓	
* If the answer to the above question is YES has the equipment been installed correctly?		* Within an interval of 6 months?				
		YES	✓	NO		
		* Within an interval of 12 months?				
		YES		NO	✓	
		* In accordance with an examination scheme?				
		YES	✓	NO		
		* After the occurrence of exceptional circumstances?				
		YES		NO	✓	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None						
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES		NO	✓
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO	✓	YES	By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None						
** Visual And Dimension Check was Carried Out.						
Is This Equipment Safe To Operate?			Yes Accept	✓	NO Reject	

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohamed Abdullah		Ashraf Alsaad	

THIS IS TO CERTIFY THAT; a competent person has examined the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.