

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB - BASRA	Certificate no:	QC-SLB-25264/01
Location:	COIL TUBING WORK SHOP	Job Order No:	QC-SLB-25264
Date of Examination:	14-Oct-2025	Next Inspection Due:	13- Apr -2026
Last Inspection		Last Proof Load Test Date	
N/A		By Manufacture	

IDENTIFICATION NO	DESCRIPTION		QTY	SWL
H228	<u>Flat 100%Polyester Webbing Sling</u> Type: Eye X Eye Manufacture: Gulf Metal Wire Industry Length: 4 M Safety Factor: 7:1 Colour: Grey 		01	Vertical 4000 kg Choker 3200 Kg Basket 8000 kg
Applicable Reference Standard:	BS EN 1492-1:+A1:2008			
* Is this the first examination after installation or assembly at a new site or location? * If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	✓	Was the examination carried out? * Within an interval of 6 months? YES ✓ NO * Within an interval of 12 months? YES NO ✓ * By an examination scheme? YES ✓ NO * After the occurrence of exceptional circumstances? YES NO ✓
	YES	✓	NO	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None				
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES	NO ✓
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO ✓ YES	By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None				
** Visual And Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept	✓	NO Reject

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Ashraf Alsaad		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.