QUALITY CONTROL	Al Takamul Company for Engineering Services Quality Control – Iraq	

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	**Certificate no:**	QC-SLB-25258-01A
Location:	RIG GW-51	**Job Order No:**	QC-SLB-25258
Date of Examination:	05-Oct-2025	**Next Inspection Due:**	04-Apr-2026
Last Inspection		**Last Proof Load Test Date**	
04/Apr/2025		After Any Repair or Modification	

Serial Number:	QTY	Description	PAYLOAD
OLU-MA5021 (A5843-14/10)	**01**	**OFFSHORE CONTAINER (MUD LOGGING UNIT)** **Dim : 4.9 m(L) X 2.41 m (W) X 2.6 m (H)** **FULLY WELDED STEEL CONSTRUCTION WITH FOUR TOP MOUNTED LIFTING POINTS** **TARE WEIGHT : 7200 kg** **MAX. GROSS WEIGHT : 9000 kg**	**1800KG**

Reference Standard:	**DNV2.7-1 &2.7-2**			
Pad Eyes Dimension:	**Thickness:**	**Pin Hole:**	**Length:**	**Height:**
	38 mm	**28 mm**	**190 mm**	**95 mm**



Is this the first examination after Installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out? Within an interval of 6 months?	YES	√	NO	
					With an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
	N/A				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect, which is or could not become a danger to persons, and a description of the defect. **NONE**				
Is the above a defect, which is of immediate danger to persons?	YES		NO	√
Is the above a defect, which is not yet but could become a danger to persons?	YES by:			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:				
Particulars of any tests carried out as part of the examination: **NONE** ** The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory ** MPI was carried out on the pad eyes Welding Areas and found satisfactory, **Check MPI Certificate No :(……) attached.**				
IS THIS EQUIPMENT SAFE TO OPERATE?	YES	√	NO	

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammad Abdullah		**Ashraf Elsaid**	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection. And considered Safe for Lifting.