

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25258-02
Location:	RIG GW-51	Job Order No:	QC-SLB-25258
Date of Examination:	05-Oct-2025	Next Inspection Due:	04-Apr-2026
Last Inspection		Last Proof Load Test Date	
04-Apr-2025		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
BA111	<u>Four Leg Wire Rope Sling.</u> Dim: 24 mm (Día) X 5.0 m (L) IWRC, MECHANICALLY SPLICED WITH STEEL FERRULE C/W MASTER LINK ASSEMBLY AT TOP HARD EYE BOTH END  SAFETY FACTOR 5:1	01	14.1 TON AT 0-38 DEG
Applicable Reference Standard:	BS EN 13414-1:2003+A2:2008		
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?		
	YES	NO	√
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?		
	YES	NO	√
	* Within an interval of 12 months?		
	YES	NO	√
	* In accordance with an examination scheme?		
	YES	NO	√
	* After the occurrence of exceptional circumstances?		
	YES	NO	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	YES
Particulars Of Any Repair, Renewal Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?	Yes Accept	√	NO Reject

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammad Abdullah		Ashraf Elsaid	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.