QUALITY CONTROL	Al Takamul Company for Engineering Services Quality Control – Iraq	

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	**Certificate no:**	QC-SLB/25262-04
Location:	D&M YARD	**Job Order No:**	QC-SLB/25262
Date of Examination:	08-Oct-2025	**Next Inspection Due:**	07-Apr-2026

Last Inspection	Last Proof Load Test Date
N/A	BY MANUFACTURE

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
H01	**Two Leg Chain Sling.** **Diameter:** 18mm **Length:** 2 m **Grade:** 80 (T) C/W Grab Connector At The End SAFETY FACTOR 5:1 	**01**	**2.0 T**

Applicable Reference Standard:	**BS EN 818-2:1996+A1:2008**							
					Was the examination carried out?			
*** Is this the first examination after installation or assembly at a new site or location?**	YES		NO	√	*** Within an interval of 6 months?**	YES	√	NO	
					*** Within an interval of 12 months?**	YES		NO	√
*** If the answer to the above question is YES has the equipment been installed correctly?**	YES	√	NO		*** By an examination scheme?**	YES	√	NO	
					*** After the occurrence of exceptional circumstances?**	YES		NO	√

Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: **None**						
Is The Above A Defect Which Is Of Immediate Danger To Persons			**YES**		**NO**	√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)	**NO**	√	**YES**		**By:**	
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: **None**						
**** Visual And Dimension Check was Carried Out.**						
Is This Equipment Safe To Operate?	**Yes Accept**	√	**NO Reject**			

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammad Abdullah		**Ashraf Elsaad**	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.