


LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATION NO:	QC-SLB-25243-05A
LOCATION:	Slick Line PCE Shop		
EXAMINATION DATE:	21/Sep/2025	JOB NO:	QC-SLB-25243
LAST INSPECTION	NEXT INSPECTION DATE		LAST PROOF LOAD TEST DATE
19/Mar/2025	20/Mar/2026		AFTER REPAIR OR ALTERATION

IDENTIFICATION NO	QTY	Description	SWL
L-690413 (SER001)	01	<u>LIFTING CLAMP</u> Lifting Clamp Assembly, Into Two Halves Bolted Together Complete Of Two Lifting Point One On Each. Constructed Of Welded Steel Plates.	3 TON
Reference Standard:	BS EN 13155 :2003+A2:2009 UNIT #017		
Lifting Cap Dimension:	Thickness:	Pin Hole:	Length:
	40mm	19mm	45 cm
			High:
			10 cm



Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES	✓	NO	
					YES		NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO		YES	✓	NO	
	N/A				YES		NO	✓

Identify any part found to have a defect, which is or could not become a danger to persons, and describe the defect. **NONE**

Is the above a defect, which is of immediate danger to persons?

YES ☐ NO ☒

Is the above a defect, which is not yet but could become a danger to persons?

YES by: ☐

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: **NONE**

** The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

** MPI was carried out on the pad eyes Welding Areas and found satisfactory **Check MPI Certificate attached.**

IS THIS EQUIPMENT SAFE TO OPERATE?

YES ☒ NO ☐

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
MOHAMMED ABDULLAH		ASHRAF ELSAAD	

THIS IS TO CERTIFY THAT; a competent person did attend the above named owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

