

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25255-06
Location:	Compilation Work Shop	Job Order No:	QC-SLB-25255
Date of Examination:	04/Oct/2025	Next Inspection Due:	03/Apr/2026
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION							QTY	SWL	
2021102	<u>Diameter:</u> 12mm <u>Length:</u> 2M IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE C/W MASTER LINK ASSEMBLY AT TOP HARD EYE AT BOTH END SAFETY FACTOR 5:1							01	25KN 2500KG AT 0-45 DEG	
										
Applicable Reference Standard:		BS EN 13414-1:2003+A2:2008								
* Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months? *		YES	√	NO	
					* Within an interval of 12 months?		YES		NO	√
* If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		* In accordance with an examination scheme?		YES	√	NO	
					* After the occurrence of exceptional circumstances?		YES		NO	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None										
Is The Above A Defect Which Is Of Immediate Danger To Persons							YES		NO	√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)					NO	√	YES		By:	
Particulars Of Any Repair, Renewal Or Alteration Required To Remedy The Defect Identified Above: None										
** Visual And Dimension Check was Carried Out.										
Is This Equipment Safe To Operate?					Yes Accept		√	NO Reject		

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohamed Abdullah		Ashraf El-saad	



THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.