

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25255-09
Location:	Compilation Work Shop	Job Order No:	QC-SLB-25255
Date of Examination:	04/Oct/2025	Next Inspection Due:	03/Apr/2026
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION										QTY	SWL
C4	<u>Single Leg Wire Rope Sling.</u> <u>DIAMETER:</u> 14mm <u>LENGTH:</u> 2M IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE HARD EYE ON BOTH ENDS. SAFETY FACTOR 5:1 										01	2.25 TON AT 0-45 DEG
Applicable Reference Standard:		BS EN 13414-1:2003+A2:2008										
* Is this the first examination after installation or assembly at a new site or location?						Was the examination carried out?						
		YES		NO	√	* Within an interval of 6 months?		YES	√	NO		
						* Within an interval of 12 months?		YES		NO	√	
* If the answer to the above question is YES has the equipment been installed correctly?		YES	√	NO		* By an examination scheme?		YES	√	NO		
						* After the occurrence of exceptional circumstances?		YES		NO	√	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None												
Is The Above A Defect Which Is Of Immediate Danger To Persons								YES		NO	√	
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)						NO	√	YES		By:		
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None												
** Visual And Dimension Check was Carried Out.												
Is This Equipment Safe To Operate?					Yes Accept			√	NO Reject			

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohamed Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.