


LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB Basra	CERTIFICATE NO:	QC-SLB-25268-09				
LOCATION:	WIRE LINE WORKSHOP		JOB NO:	QC-SLB-25268			
EXAMINATION DATE:	18/Oct/2025						
LAST INSPECTION		NEXT INSPECTION DATE		LAST PROOF LOAD TEST DATE			
N/A		17/Apr/2026		By Manufacture			
IDENTIFICATION NO	DESCRIPTION			QTY			
LC-06	<u>DRUM CLAMP INTEGRATED WITH 2-LEG CHAIN</u> CHAIN SIZE: 6.3mm LENGTH: 516 mm MANUFACTURE: TOYO EQUIPPED WITH: TWO CLAMP LOWER TERMINATION SPREADER CLAMP LINK UPPER TERMINATION.			01			
					1 TON		
Applicable Reference Standard:	BS EN 818-2:1996+A1:2008						
* Is this the first examination after installation or assembly at a new site or location?	YES		NO		✓		
* If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		✓		
Was the examination carried out?							
		* Within an interval of 6 months?		YES	✓	NO	
		* Within an interval of 12 months?		YES		NO	✓
		* By an examination scheme?		YES	✓	NO	
		* After the occurrence of exceptional circumstances?		YES		NO	✓
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None							
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES		NO	✓	
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO	✓	YES	By:	
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None							
** Visual And Dimension Check was Carried Out.							
Is This Equipment Safe To Operate?		Yes Accept	✓	NO Reject			

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohamed Abdallah		ASHRAF ELSAAD	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

