



Al Takamul Company for Engineering Services
Quality Control – Iraq

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25274-09
Location:	WIRELINE WORKSHOP	Job Order No:	QC-SLB-25274
Date of Examination:	26/Oct/2025	Next Inspection Due:	25/Apr/2026
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
1249	FLAT WEBBING SLING Material: Polyester Length: 2 M Manufacturer: DELTAPLUS Safety Factor: 7:1 Colour: Green 	02	VERTICAL 2000 kg CHOKER 1600 Kg BASKET 4000 kg
Applicable Reference Standard:	BS EN 1492-1:2000+A1:2008		
* Is this the first examination after installation or assembly at a new site or location?			Was the examination carried out?
	YES	NO	* Within an interval of 6 months?
			* Within an interval of 12 months?
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	* By an examination scheme?
			* After the occurrence of exceptional circumstances?
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?	Yes Accept		NO Reject

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khalid Mahmood		Mohammad Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

