

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB Basra	CERTIFICATION NO:	QC-SLB-25249-13																
LOCATION:	WIRE LINE WORKSHOP	JOB NO:	QC-SLB-25249																
EXAMINATION DATE:	30/Sep/2025																		
LAST INSPECTION	NEXT INSPECTION DATE	PROOF LOAD TEST DATE																	
19/Mar/2025	29/Mar/2026	BY MANUFACTURE																	
IDENTIFICATION NO	DESCRIPTION	QTY	SWL																
NE2733 NE2732	<u>Single Leg Wire Rope Sling.</u> Dim: 13 mm (Dia) X 18 ft (L) IWRC, 6 X 36 MECHANICALLY SPLICED WITH STEEL FERRULE HARD EYE AT BOTH END SAFETY FACTOR 5:1 	02	2 TON																
Applicable Reference Standard:	BS EN 13414-1:2003+A2:2008 UNIT # 048																		
* Is this the first examination after installation or assembly at a new site or location?	<table border="1"> <tr> <td>YES</td> <td>NO</td> <td>✓</td> </tr> </table>			YES	NO	✓													
YES	NO	✓																	
* If the answer to the above question is YES has the equipment been installed correctly?	<table border="1"> <tr> <td>YES</td> <td>✓</td> <td>NO</td> </tr> </table>			YES	✓	NO													
YES	✓	NO																	
Was the examination carried out?																			
<table border="1"> <tr> <td>* Within an interval of 6 months?</td> <td>YES</td> <td>✓</td> <td>NO</td> </tr> <tr> <td>* Within an interval of 12 months?</td> <td>YES</td> <td></td> <td>NO</td> </tr> <tr> <td>* By an examination scheme?</td> <td>YES</td> <td>✓</td> <td>NO</td> </tr> <tr> <td>* After the occurrence of exceptional circumstances?</td> <td>YES</td> <td></td> <td>NO</td> </tr> </table>				* Within an interval of 6 months?	YES	✓	NO	* Within an interval of 12 months?	YES		NO	* By an examination scheme?	YES	✓	NO	* After the occurrence of exceptional circumstances?	YES		NO
* Within an interval of 6 months?	YES	✓	NO																
* Within an interval of 12 months?	YES		NO																
* By an examination scheme?	YES	✓	NO																
* After the occurrence of exceptional circumstances?	YES		NO																
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None																			
Is The Above A Defect Which Is Of Immediate Danger To Persons																			
<table border="1"> <tr> <td>YES</td> <td>NO</td> <td>✓</td> </tr> </table>				YES	NO	✓													
YES	NO	✓																	
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)																			
<table border="1"> <tr> <td>NO</td> <td>✓</td> <td>YES</td> <td>By:</td> </tr> </table>				NO	✓	YES	By:												
NO	✓	YES	By:																
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None																			
** Visual And Dimension Check was Carried Out.																			
Is This Equipment Safe To Operate?																			
<table border="1"> <tr> <td>Yes Accept</td> <td>✓</td> <td>NO Reject</td> </tr> </table>				Yes Accept	✓	NO Reject													
Yes Accept	✓	NO Reject																	
INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:																
Mohammad Abdullah		Ashraf Elsaad																	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

