

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB/25262-15
Location:	D&M YARD	Job Order No:	QC-SLB/25262
Date of Examination:	10-Oct-2025	Next Inspection Due:	09-Apr-2026
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION						QTY	SWL			
AX4268	<u>Two Leg Wire Rope Sling.</u>						01	1.14 TON AT 0-45 DEG			
	Dim: 8 mm (Día) X 2.2 Ft (L)										
	IWRC, MECHANICALLY SPLICED WITH STEEL FERRULE C/W MASTER LINK ASSEMBLY AT TOP HARD EYE BOTH END										
SAFETY FACTOR 5:1											
Applicable Reference Standard:		BS EN 13414-1:2003+A2:2008									
* Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?							
	YES		NO	√	Within an interval of 6 months? *		YES	√	NO		
				* Within an interval of 12 months?		YES		NO	√		
* If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		* In accordance with an examination scheme?		YES	√	NO		
	N/A			* After the occurrence of exceptional circumstances?		YES		NO	√		
	Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None										
Is The Above A Defect Which Is Of Immediate Danger To Persons						YES			NO	√	
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)					NO	√	YES		By:		
Particulars Of Any Repair, Renewal Or Alteration Required To Remedy The Defect Identified Above: None											
** Visual And Dimension Check was Carried Out.											
Is This Equipment Safe To Operate?				Yes Accept		√	NO Reject				

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammad Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.