



LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB Basra	CERTIFICATION NO:	QC-SLB-25249-16		
LOCATION:	WIRE LINE WORKSHOP		JOB NO:	QC-SLB-25249	
EXAMINATION DATE:	30/Sep/2025				
LAST INSPECTION		NEXT INSPECTION DATE		PROOF LOAD TEST DATE	
19/Mar/2025		29/Mar/2026		BY MANUFACTURE	
IDENTIFICATION NO	DESCRIPTION			QTY	
NE2670	<u>MASTER LINK</u> Dim : 193 mm X 100 mm Safety Factor : 4:1 Manufacture : GPT Grade: 8  ATTACHED WITH SPREADER PLATE #L-632071-075M			01	
				10 TON	
Applicable Reference Standard:	SLB Mechanical Lifting Standard / US FED SPEC RR-C-27 1 D / BS EN 1677-4				
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?				
	YES	NO	✓		
	* Within an interval of 6 months?		YES	✓	
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 12 months?		YES	✓	
	* By an examination scheme?		YES	✓	
	* After the occurrence of exceptional circumstances?		YES	✓	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None					
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES	NO	
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO	YES	
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None					
** Visual And Dimension Check was Carried Out.					
Is This Equipment Safe To Operate?		Yes Accept	✓	NO Reject	

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammad Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person has examined the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested and found to comply with the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.