




Al Takamul Company for Engineering Services
Quality Control – Iraq

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB/25262-17
Location:	D&M YARD	Job Order No:	QC-SLB/25262
Date of Examination:	10-Oct-2025	Next Inspection Due:	09-Apr-2026
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION						QTY	SWL		
F7172 F7173	<u>Safety pin bow Shackles</u> <u>Diameter:</u> 3/4’’ <u>Grade:</u> 6 <u>Manufacturer:</u>CROSBY 						02	4.75 TON		
Applicable Reference Standard:	BS EN 13889									
* Is this the first examination after installation or assembly at a new site or location?	YES				NO				Was the examination carried out?	
	YES				NO				* Within an interval of 6 months?	
	YES				NO				* Within an interval of 12 months?	
* If the answer to the above question is YES has the equipment been installed correctly?	YES				NO				* By an examination scheme?	
	YES				NO				* After the occurrence of exceptional circumstances?	
	YES				NO				YES	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None										
Is The Above A Defect Which Is Of Immediate Danger To Persons							YES		NO	
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)					NO		YES		By:	
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None										
** Visual And Dimension Check was Carried Out.										
Is This Equipment Safe To Operate?					Yes Accept		NO Reject			

LEEA & ASNT Level II Inspector Name:		Authenticating This Report:	SIGNATURE:
Mohammad Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.